

ABSTRACT

The farmers are required to spend great sums of money on labour cost etc, for the purpose threshing paddy. In addition to that, they are also expected to devote more time and use other machines to it. This high capacity thresher has been made to meet all these requirements at once utilizing lesser amount of time.

The aim of this is to rectify the disorders of the oscillating unit, the tear wear position of the pegs and of protecting bearing and gear wheel by putting a cover of over it. I was entrusted with the task of repairing the unit doing the needful.